

Work Order ID 149030***149030***

Page 1

Thursday, July 13, 2017 8:39:53 AM

Item ID: D5156-3 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Face Plate
Start Date: 7/27/2016 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 7/28/2016 Req'd Qty: 1.00 ***1*** Customer: CCONS01
Reference: RMA RA112115

Approvals: Process Plan:  Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D5156	B								

100

0.00

100

QC

Quality Control

Memo


INSPECT RMA RA112115

SCRAP

1 X D5156-3 B132808

0.00

① 17-07-13 DAS
9
9-89

 17/7/17 
JUL 13 2017

Picklist Print

Page 1

Thursday, July 13, 2017 8:39:51 AM

Work Order ID: 149030

149030

Parent Item: D5156-3

D5156-3

Parent Item Name: Face Plate

Start Date: 7/27/2016

Required Date: 7/28/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP REV:A 15.05.07 NEW ISSUE DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D5156-3 *D5156-3* Face Plate		Manufactured	No				Each	9.0000	**	1			DAS 9 9-89
				<u>Location</u>				<u>Loc Qty</u>					
				ST155				9					
				143376				9					

Inspection Sheet Not Complete
RA112115

[illegible]